

**Power Train Components** 

YOUR PARTNERS FOR PROFIT!

## **Eliminate Transmission Pan Leaks The First Time - Every Time**

with Premium Black Accopac Transmission Pan Gaskets

Traditional cork-rubber compound transmission pan gaskets can be subject to leaks because they have limited flexibility to conform to pan irregularities and can easily be crushed and crack if the pan is torqued down too much.



Leak due to gasket not conforming to pan irregularities




Split gasket caused by over torquing

Avoid these common problems with PTC's Transmission Filter Kits with ACCOPAC gaskets.

Note: The Accopac Gasket line is in addition to our current PTC Transmission filter kit program.

**Increase Your Gasket** Profitability by Providing a Premium Solution



**Proudly Made in the USA** 



## **KEY FEATURES INCLUDE:**

- Made of premium 1/16" thick Nitrile Cellulose material for long life
- Can be torqued up to 45 ft. lbs. Will not split, crack or break
- Increased flexibility and fluid resistance; will easily conform to pan irregularities
- No silicone sealant required!
- Readily conforms to irregular surfaces to permanently seal used pans
- Will not crack, break or embrittle, due to extreme temperatures (up to 350°F) or prolonged storage
- Gasket material will swell after installation, further improving transmission pan sealability
- Material can be laid out flat, without cracking or breaking, after prolonged periods on the shelf
- 193 numbers available to provide over 90% market coverage

Call us today at 800.626.8333 to Order Your Needs!