

Power Train Components

YOUR PARTNERS FOR PROFIT!



New 50000 Series Complete Hub Assemblies

Now Available

Don't Replace the Bearing – Replace the Entire Assembly!

Take advantage of these unique sales opportunities from PTC. Most competitors only offer the bearing for the import applications referenced below. Why settle for a bearing replacement that requires more shop time and potential human error to install when you can simply replace the entire hub assembly.

- OE-Design, fit and function for easy installation and long dependable performance
- Each hub includes water-tight seals containing premium long-life grease
- Improved dimensional end testing to ensure end play meets OE standards (end play is the key parameter to controlling noise)
- ABS sensor testing eliminates connection problems

				- 1															_	-																		
u	-	w	٧.	~	^	ш	71		١.		_	٠.	_		ш	п			v.	T.	а.		71	-	Ц	ι.		. ,		v.	,,	ш		//\				
м	100	١,,	w			IV	771	-		13			-	=			=1	■ 4		1	М.	ע ב	٠, ١	151		1 =			4 N	м	/ A)	٧I		м	12			
N	-	N /	M	~	u	11	41		-	15	7		_		ĸ.	•	-,1			\mathbf{r}		- 1	41	ш.	-		₹.		-۱	v.	_	u	_	-	١	-	_	

	PTC No.	Applications
	PT50001	Lexus GX460 2015-10, GX470 2009-03; Toyota 4Runner 2015-03, FJ Cruiser 2014-07, Tacoma 2015-05
	PT50002	Toyota Sequoia 2018-08, Tundra 2018-07
	PT50003	Acura CL 1997; Honda Accord 1997-90
	PT50004	Toyota 4Runner 2016-03, FJ Cruiser 2009-07, Tacoma 2015-05
	PT50006	Toyota Sequoia 2018-08, Tundra 2018-07
	PT50008	Infiniti FX35 2008-03



REPLACEMENT FORD TRUCK SPINDLE NUT NOW AVAILABLE

- OE fit and performance
- One-time spindle nut hardware OE design

PTC No.	OE Number	Applications
F15170	6Z3Z3C294AA	Ford F-150 RWD Front 2004-2008 Lincoln Mark LT RWD Front 2006-2008
F15170-2 (2 pack)	6Z3Z3C294AA	Ford F-150 RWD Front 2004-2008 Lincoln Mark LT RWD Front 2006-2008

DO NOT REUSE — REPLACE!

This part cannot be reused and needs to be replaced every time it's removed during service of the vehicle



Call us today at 800.626.8333 to Order Your Needs!